COPY FOR YOUR INFORMATION

U.S. Department of Transportation
Federal Aviation Administration

Aircraft Certification Service
Compliance & Airworthiness Division

Atlanta ACO Branch
1701 Columbia Ave.
College Park, GA 30337

February 21, 2020

In reply, refer to FAA Correspondence # 7A0-20-2447

Mr. Adam Williams
Airworthiness Branch
National Operations and Standards Division
CASA\Aviation Group
12-14 The Circuit, Brisbane Airport QLD 4007
GPO Box 2005, Canberra ACT 2601

Dear Mr. Williams:

Lifesaving Systems Corporation (LSC), a U.S. company, requested that the Atlanta ACO Branch review the design of their product for compliance with the performance standards of ATSO-C1001 Dispatcher's Restraint Strap.

The ACO has completed a review of the technical data pertaining to the design and testing of Aviation Crewman Safety Belt model 219 against the minimum performance standards of ATSO-C1001 and the applicable sections of AS/NZS 1891.1:1995 Amdt 5. In accordance with the Implementation Procedures for Airworthiness article 3.0.6.0, 3.0.6.1(d) and CASR 21.617 (1) (a), we certify that the subject article meets the requirements of ATSO-C1001 dated 16 June 2000.

Please contact Dan McCully at (404) 474-5548 or at william.mccully@faa.gov regarding the electronic transfer of additional LSC technical data listed in attachment (**3**) in accordance with CASR 21.617 (1) (b).

Sincerely,

(for)
Christina M. Underwood
Manager, Atlanta ACO Branch

Attachments:
(1) LSC Letter dated January 13, 2020
(2) CASA Form 724 (219)
(3) LSC Document F-730-219

Cc: Thomas Beach